



Care of Sanitary Surfaces

All REOTEMP 3-A marked sanitary instruments have carefully prepared *Wetted Surfaces*. These surfaces contain no cracks or crevices where germs could breed, and they are polished to a maximum roughness average (Ra) of 32.

The “wetted surfaces” of an instrument are the surfaces that will come in contact with your process fluid. Consult the diagrams below to see the wetted surface for the instrument you have received.



All REOTEMP sanitary instruments are shipped with packaging that protects the wetted surfaces. To preserve the sanitary compliance of the instrument, **CARE SHOULD BE TAKEN** to prevent any scratching, denting, or abrasion of the wetted surfaces prior to or during installation.

10656 Roselle St. San Diego, CA - 92121
Ph: (858)784-0710 - Fx: (858)784-0720
www.reotemp.com email: sales@reotemp.com