

Data Logging Heat Stress Meter Model R6250SD



TECHNICAL DATA

Features

- Measures temperature, humidity, dew point, wet bulb, black globe, indoor/outdoor WBGT
- Wet Bulb Globe Temperature (WBGT) considers the effects of temperature, humidity and direct or radiant sunlight
- In/Out function displays the WBGT value with or without direct sun exposure
- Black Globe Temperature (TG) monitors the effects of direct solar radiation on an exposed surface
- Adjustable audible alarm
- User selectable unit of measure (°F or °C)
- Data hold and Max/Min functions
- · Real-time datalogger with integrated SD memory card
- User selectable sampling rate from 1 to 3600 seconds
- Easy-to-read backlit LCD display
- Tripod mount for long-term monitoring
- · Low battery indicator and auto shut off
- Includes soft carrying case & batteries

Specifications

Temperature

Measuring Ranges: Air: 32 to 122.0°F (0 to 50.0°C)

Dew Point: -13.5 to 120.1°F

(-25.3 to 48.9°C)

Wet Bulb: -6.9 to 122.0°F

 $(-21.6 \text{ to } 50^{\circ}\text{C})$

Black Globe: 32 to 176°F

(O to 80°C)

Indoor WBGT: 32 to 138°F

(O to 59°C)

Outdoor WBGT: 32 to 132°F

(O to 56°C)

Accuracy: Air: ± 1.5 °F (± 0.8 °C)

Black Globe: ±1.1°F (±0.6°C) Indoor WBGT: ±2.7°F (±1.5°C) Outdoor WBGT: ±3.6°F (±2°C)

Resolution: 0.1°F/°C

Humidity

Measuring Range: 5 to 95% RH

Accuracy: >70% RH: ±(3% rdg + 1% RH)

<70% RH: ±3% RH

Resolution: 0.1% RH







Continued...



Data Logging Heat Stress Meter Model R6250SD



TECHNICAL DATA

General Specifications

Indoor Formula: 0.7WB + 0.3TG

Indoor Range: 32 to 138°F (O to 59°C)

Indoor Accuracy: $\pm 2.7^{\circ}F (\pm 1.5^{\circ}C)$

Outdoor Formula: 0.7WB + 0.3TG + 0.1TA Outdoor Range: 32 to 132°F (O to 56°C)

Outdoor Accuracy: ±3.6°F (±2°C)
Response Time: 1 second
Display: 4-digit dual LCD

Backlit Display: Yes
Data Hold: Yes
Min: Yes
Max: Yes
Datalogging Capabilities: Yes

Real-Time Clock and

Date Stamp: Yes

Selectable Sampling Rate: Yes (1, 2, 5, 10, 30, 60, 120,

300, 600, 1800, 3600 seconds)

External Memory: Yes, expandable up to 16GB

with SD card (optional)

Auto Shut-off: Yes (after 10 minutes/off)

Kick Stand: Yes
Tripod Mountable: Yes
Low Battery Indicator: Yes

Power Supply: 6 x AA batteries or

AC Adapter (optional)

Data Output: Yes (RS-232)

Product Certifications: CE

Operating Temperature: 32 to 122°F (O to 50°C) Storage Temperature: 14 to 140°F (-10 to 60°C)

Operating Humidity Range: 10 to 85%

Dimensions: Instrument: 7.0 x 2.7 x 1.8"

(177 x 68 x 45 mm) Black Brass Ball Diameter:

2.9" (75mm)

Weight: 1.1lb (515g)

R6250SD-KIT

Data Logging Heat Stress Meter with Power Adapter and SD Card

Includes:

R6250SD Data Logging Heat Stress Meter, RSD-16GB 16GB Micro SD Memory Card with adapter and RSD-ADP-NA AC Power Adapter



R6250SD-KIT2

Data Logging Heat Stress Meter with Tripod, SD Card and Power Adapter

Includes:

R6250SD Data Logging Heat Stress Meter, R1500 Tripod, RSD-16GB 16GB Micro SD Memory Card with adapter and RSD-ADP-NA AC Power Adapter

ripod,

R6250SD-KIT3

Data Logging Heat Stress Meter with Tripod Kit

Includes:

R6250SD Data Logging Heat Stress Meter, RSD-16GB 16GB Micro SD Memory Card with adapter, R1500 Tripod and 2590-8024REED

Water Bottle



Model	Description
R6250SD	Data Logging Heat Stress Meter
R1500	Tripod
RSD-ADP-NA	Power Supply, 110V
RSD-ADP-EU	Power Supply, 220V
CA-05A	Soft Carrying Case
R8888	Hard Carrying Case
SD-4GB	4GB Class 4 SDHC Memory Card
RSD-16GB	16GB Micro SD memory Card w/Adapter
R6250SD-KIT	Data Logging Heat Stress Meter with Power Adapter and SD Card
R6250SD-KIT2	Data Logging Heat Stress Meter with Tripod, SD Card and Power Adapter
R6250SD-KIT3	Data Logging Heat Stress Meter with Tripod Kit
R6250SD-NIST	Data Logging Heat Stress Meter with NIST